


Comments. : Information remains as inspection date. : 2015.10.09. On the southbound carriageway NE combe plate No 4. Very noisy now, Banging when heavy vehicles pass over .Requires attention.

On the Southbound Carriageway SE4 – Repaired on Nightshift by engineer S. West. 2015.10.20. Southbound Carriageway SE2 – there is slight movement / slight noise evident – will monitor. Plate noisier on this inspection will require attention soon.

Northbound Carriageway SW2 - there is movement/ noise evident.

H:\Viaduct Expansion Joint Weekly Inspections 2015\Combe Plate Weekly Survey Sheet 2015.10.23..Doc



Combe plate weekly survey sheet DATE. 2015.10.23..

