

Comments. : Information remains as inspection date. : 2015.10.09. On the southbound carriageway NE combe plate No 4. Very noisy now , Banging when heavy vehicles pass over .Requires attention.

On the Southbound Carriageway

Southbound Carriageway SE2 – there is slight movement / slight noise evident – will monitor. <u>Plate noisier on this</u> inspection will require attention soon.

Northbound Carriageway - SW2 . Repaired on Nightshift by engineer S. West. 2015.10.20.

H:\Viaduct Expansion Joint Weekly Inspections 2015\Combe Plate Weekly Survey Sheet 2015.10.28..Doc





Combe plate weekly survey sheet DATE. 2015.10.28.