



STAGING REQUESTED: FOR INSPECTION TO POTENTIAL WELD CRACK TO CYCLE TRACK SOFFIT, LOCATED AT P.P.64 S.E.