

General Inspection Report

(BC06)

REPORT No.178

DATE: 12/10/2004 TO 13/10/2004

EXPANSION JOINT (CYCLE TRACK)

THE CYCLE TRACK EXPANSION JOINTS AT BOTH THE NORTH & SOUTH MAIN TOWERS (BOTH MAIN SPAN & SIDE SPANS) WERE VISUALLY INSPECTED OVER

THE ABOVE DATES, GENERAL FINDINGS WERE AS FOLLOWS. :

TOPSIDE. : STATUS WITH REGARDS TO WEARDOWN ON THE SLIDING PLATES &

APRON PLATES REMAIN AS PREVIOUS REPORTS. THE ABOVE WEAR CONTINUES

TO HAVE AN EFFECT ON THE BITUMOUS SURFACE BELOW.

PHOTOGRAPHIC

EXAMPLES ON FRB\DATA DRIVE (P), MAINT & CAPITAL, BC09 MAIN TOWERS

& PIERS.

UNDERSIDE. : ALL PLATEWORK AND FIXINGS REMAIN IN A SATISFACTORY CONDITION.

ALL DEFECTS DETAILED & ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTOR. : K.N.Perryman.