

General Inspection Report

(BC07)
Report No.5

MAIN CABLE

DATE: 18/11/1996 TO 11/12/1996

The main cables were visually inspected from south anchorage chamber through to north anchorage chamber on both east and west sides of bridge. the main cable was found to be generally satisfactory with exception of a few minor defects which are listed in individual inspection reports. note ; inspection limited to top section of cable only