General Inspection Report

(BC13) REPORT No.110 SIDE TOWERS N & S

DATE: 07/03/2002 TO 15/03/2002

BOTH THE NORTH & SOUTH SIDE TOWERS WERE VISUALLY INSPECTED OVER AN INTERMITTANT PERIOD BETWEEN THE ABOVE DATES, GENERAL FINDINGS WERE AS FOLLOWS:

GENERALLY: THE STRUCTURAL CONDITION APPEARS SATISFACTORY.

<u>POST TENSIONED CABLES:</u> SINCE THE LAST INSPECTION, DUE TO THE CONTINUING DETERIORATION OF THE POST TENSIONED CABLES, UNDER THE INSTRUCTION OF THE D.G.M. B. COLFORD, CABLE INSPECTIONS ARE NOW CARRIED OUT QUARTERLY. FOR LATEST STATUS, PLEASE REFER TO ATTACHED SURVEY SHEET.

ALL DEFECTS ARE DETAILED & ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTORS: