

General Inspection Report

(BC16)
REPORT No.150
SUSPENDERS

DATE: 17/09/2003 TO 24/09/2003

ALL ROPES, SPACERS AND TOP CHORD ASSEMBLIES ON THE SIDE SPANS AND MAIN SPAN, BOTH EAST & WEST WERE VISUALLY INSPECTED OVER AN INTERMITTENT PERIOD BETWEEN THE ABOVE DATES.

THE USE OF OPTICAL AID EQUIPMENT FOR DETAILED INSPECTION WAS USED AS REQUIRED. ALL ITEMS WERE FOUND TO BE IN SATISFACTORY CONDITION WITH NO DEFECTS REPORTED ON THE STRUCTURE REPORT PROGRAMME.

BRIDGE INSPECTOR. :