

General Inspection Report

(BC13)

REPORT No. 164
SIDE TOWERS N & S

DATE: 16/02/2004 TO 27/02/2004

BOTH THE NORTH & SOUTH SIDE TOWERS WERE VISUALLY INSPECTED OVER AN INTERMITTENT PERIOD BETWEEN THE ABOVE DATES, GENERAL FINDINGS WERE AS FOLLOWS :

GENERALLY : THE SIDE TOWER STRUCTURES APPEAR IN A SATISFACTORY CONDITION, WITH ONLY **6in No** ELEMENT DEFECTS RECORDED.

STAGINGS & LADDERS & HANDRAILS. : ALL STAGINGS, LADDERS & ALL HANDRAILS THROUGHOUT ALL LEVELS OF ALL FOUR SIDE TOWERS HAVE BEEN PAINTED OR ARE IN THE PROCESS OF BEING PAINTED SINCE LAST INSPECTION.

POST- TENSIONED CABLES. : CABLE **E4** IN THE **SOUTH SIDE TOWER EAST LEG** HAS BEEN CUT FROM **BASE LEVEL** TO **LEVEL 1**, CABLE LYING ON BASE LEVEL FLOOR. CABLE **E9** STRAND BREAKAGE HAS TO **6 in No.** (PLEASE REFER TO POST TENSION CABLE SURVEY SHEET FOR CURRENT STATUS.)

ALL DEFECTS ARE DETAILED & ENTERED ON THE STRUCTURE REPORT PROGRAMME.

INSPECTORS :