

General Inspection Report

(BC16)
REPORT No.182
SUSPENDERS

DATE: 23/11/2004 TO 26/11/2004

The ropes, spacers & castings / top chord assemblies on the Side spans and the Main span both East & West were visually inspected between the above dates. :

Where required the use of Optical Aid equipment for detailed inspection was carried out with the exception of the ropes & castings / top chord assemblies at the following locations: **PP. 02 S/W. Side span, PP. 02 N/E Side span, PPs. 100 S/W & N/W Main span & PPs, 100 S/E Main span.** (The above exceptions were Due to Main cable inspection /survey Works being carried out by contractors Charles Spencer / Faber Maunsel the afore mentioned positions were unable to be accessed therefore no inspection at these locations was carried out.)

All items were found to be in a satisfactory condition with no defects recorded on the Structure report programme.

Inspectors. :