KINGPOST DEFECTS AS OF 06/04/09

P.P. 48 NORTH SHEARED CONNECTION BOLTS AT TOP JOINT.

P.P.54 NORTH SHEARED KINGPOST TOP JOINT.

P.P.68 NORTH SHEARED KINGPOST TOP JOINT.

P.P.92 SOUTH SHEARED CONNECTION BOLT X1, $2^{\rm ND}$ BOLT SUSPECT BOTTOM CONNECTION.