



INSPECTION DEPARTMENT
Trailer Incident. PP. 80 N/E
DATE. 2014.07.30

Trailer incident. PP. 80 North East Main span. 2014.07.29.

Following an incident which on the Main-span carriageway at the above location at approximately 15.00 hours where a small billboard trailer being towed over-turned . Bridge Inspection staff were requested to attend to assess any damage which may have occurred. On arrival, due to the heavy traffic volume the incident had been dealt with therefore it was not possible to assess any damage from the carriageway. Communication with bridge operations staff who attended reported no damage was evident. However the following day Bridge Inspectors decided to assess for any damage. This proved to be a positive. A full visual inspection of the deck panel was carried out from the top chord. As pictures show the roadwork sign fold- in post was badly distorted and will need to be replaced. Work May Be Required To Top And Bottom handrail Location Brackets as slight Distortion Evident. Individual defect sheet has been drafted and passed on to the maintenance inspector to issue for required work to be carried out.



Sign Post Fold In Type Located On Handrail At Pp 80 N/E . Impact Damage Following Trailer Incident On 2014.07.29. Requires To Be Replaced . Work May Be Required To Top And Bottom Handrail Location Brackets. Slight Distortion Evident.



Bridge Inspector