Cable Band Bolt Assemblies

Main Points for BBC News Item

- Cracks found in nuts forming part of cable band bolts during inspection by FRB staff
- Important structural members as they connect vertical hangers which support the deck to the main cables
- Some work requires to be carried out now to prevent more serious problems potentially developing in the future
- Needs some carriageway closures to ensure safety of users as involves lifting beams and winch frames 90 m up onto the main cables over the carriageway.
- Least disruptive weekend mornings first light to around 12 noon
- Some delays to traffic which are likely to be significant
- This weekend and following weekends if possible use public transport delay journey use alternative route.
- Weather or unforeseen issues may delay so websites forth road bridge traffic scotland in search engines