




INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.07.31.



Comments. :

On this inspection noise prominent on combe plate SE 2. – Requires to be attended to.

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out

On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over  
Southbound Carriageway SE2 – there is slight movement on the west side.

Inspectors. : .....

Date.: .....



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.07.31.