



Walkway support bracket lindaptors on both e & w side of support beam require to be tightened movement no clamping