

INSPECTION DEPARTMENT

Main Tower Expansion Joints North & South DATE. 07.02.12

(BC06) REPORT No 349. MAIN SPAN EXPANSION JOINTS N & S

DATE: 06.02.12 to 07.02.12

A visual inspection of the North and South Main Tower expansion joints was carried out on the above dates, information and current status is as follows:

**Information:** On the 8<sup>th</sup> October 2011 inspection of the current condition of the South Main Tower expansion joint plates ME3 & SE3 were carried out and associated repairs and remedial works, if required, before plates were reinstated back into position. It should be recorded however, that no refurbishment work was required to be carried out on any of the plates, only cleaning operations to remove excessive detritus from plate seats to ensure that no problems were encountered during reinstatement.

**<u>Structural Steelwork:</u>** All the steelwork generally remains in a satisfactory condition.

**Fixings:** All associated fixings remain intact and secure. Protective covering breakdown is evident with medium to heavy corrosion on the bolt heads also evident at time of inspection.

**<u>Pins, Springs & Bushes:</u>** All these remain in a satisfactory condition, although the pins and bushes located in plate ends still show a state of deterioration.

<u>Surface Plates:</u> Surface plate located above cell ME5 (South Tower - East Side) gave indications of a slight noise during the inspection. On further investigation from above wear-down was evident, possible indication of a weld crack, will investigate further.

**Spring Dimensions:** Spring dimensions taken on all Rocker and Tongue Plate springs, all remain in a satisfactory condition. There was evidence of paint breakdown at time of inspection. (Survey Sheet attached)

<u>Access Platform:</u> Nut missing from upper access platform steelwork, the bolt is housed below the access cover plate, D. Bishop has been notified (photograph attached).

Bridge Inspectors:

F:\E Engineering\E2 - Inspections\E2.1 Bridge\Joints\Main Tower Demag Expansion Joints\General Reports\General report No 349 South Tower Main Expansion Joint. 07.02.12\Main Tower Expansion Joints N & S Report 349 07.02.12.doc



## INSPECTION DEPARTMENT

South main tower Main tower expansion joint spring checks

DATE. 07.02.12

DIMENSION OF SPRING CHECK. 21/07/11.							
SOUTH EAST (MAINSPAN)	MEI	ME2	ME3	ME4	ME5	ME6	
ROCKER PLT. SPRING COMPRESSION DIM.	139 mm	139 mm	135 mm	138 mm	138 mm	138 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	68 mm	69 mm					
TONGUE PLT. SPRING /W COMPRESSION DIM.	69 mm	69 mm	68 mm	69 mm	69 mm	69 mm	
DIMENSION OF SPRING CHECK . 23/01/11.							
SOUTH EAST (SIDESPAN)	SEI	SE2	SE3	SE4	SE5	SE6	
ROCKER PLT. SPRING COMPRESSION DIM.	138 mm	139 mm	139 mm	139 mm	139 mm	138 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	69 mm						
TONGUE PLT. SPRING /W COMPRESSION DIM.	69 mm	68 mm	65 mm	69 mm	69 mm	68 mm	

DIMENSION OF SPRING CHECK . 21/07/11.							
SOUTH WEST(MAINSPAN)	MWI	MW2	MW3	MW4	MW5	MW6	
ROCKER PLT. SPRING COMPRESSION DIM.	139 mm	139 mm	138 mm	138 mm	139 mm	138 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	68 mm	68 mm	68 mm	68 mm	68 mm	68 mm	
TONGUE PLT. SPRING /W COMPRESSION DIM.	67 mm	68 mm	68 mm	68 mm	68 mm	68 mm	
	DIMENSI	ON OF SPRIN	G CHECK . 23	/01/11.			
SOUTH WEST(SIDESPAN)	SWI	SW2	SW3	SW4	SW5	SW6	
ROCKER PLT. SPRING COMPRESSION DIM.	138 mm	139 mm	139 mm	138 mm	138 mm	138 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	68 mm	68 mm	68 mm	68 mm	68 mm	68 mm	
TONGUE PLT. SPRING /W COMPRESSION DIM.	66 mm	68 mm	68 mm	68 mm	68 mm	69 mm	

F:\E Engineering\E2 - Inspections\E2.1 Bridge\Joints\Main Tower Demag Expansion Joints\General Reports\General report No 349 South Tower Main Expansion Joint. 07.02.12\South Main Tower Expansion Joint Spring sizes.07.02.12.doc



## INSPECTION DEPARTMENT

S/M/Tower expansion joint access platform. Adjacent to S/E 6. DATE. 07/02/12



Nut missing from of upper access platform steelwork bolt . Bolt, which is housed below access cover plate as shown in photograph No 2.



SOUTH MAIN TOWER EXPANSION JOINT FAILSAFE SYSTEM. DATE: 07.02.12



## Expansion Joint Failsafe System South main tower expansion joint.

	ROCKER PLATE SPRINGS & PINS	FIXINGS	TONGUE PLATE SPRINGS & PINS		
SOUTH WEST SIDE SPAN					
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.W. <b>2</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.W. <b>3</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.W. <b>4</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.W. <b>6</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
SOUTH EAST SIDE SPAN					
S.E. <b>1</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.E. <b>2</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.E. <b>3</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.E. <b>4</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.E. <b>5</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
S.E. <b>6</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
SOUTH WEST MAIN					
SPAN					
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.W. <b>2</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.W. <b>4</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.W. <b>5</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
SOUTH EAST MAIN					
SPAN					
M.E. <b>1</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.E. <b>2</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.E. <b>3</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.E. <b>4</b>	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.		
Signed by Inspector. :		T. Liebisch			
Comments. ;					

F:\E Engineering\E2 - Inspections\E2.1 Bridge\Joints\Main Tower Demag Expansion Joints\General Reports\General report No 349 South Tower Main Expansion Joint. 07.02.12\South Expansion Joint Failsafe System Inspection 07.02.12.doc





DIMENSION OF SPRING PRE-COMPRESSION							
NORTH EAST (MAINSPAN)	MEI	ME2	ME3	ME4	ME5	ME6	
ROCKER PLT. SPRING COMPRESSION DIM.	139 mm	139 mm	137 mm	140 mm	140 mm	138 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	72 mm	71 mm	71 mm	70 mm	72 mm	71 mm	
TONGUE PLT. SPRING /W COMPRESSION DIM.	71 mm	72 mm	71 mm	72 mm	72 mm	70 mm	
DIMENSION OF SPRING CHECK							
NORTH EAST(SIDESPAN)	SEI	SE2	SE3	SE4	SE5	SE6	
ROCKER PLT. SPRING COMPRESSION DIM.	140 mm	137 mm	140 mm	138 mm	138 mm	138 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	68 mm	68 mm	71 mm	67 mm	67 mm	67 mm	
TONGUE PLT. SPRING /W COMPRESSION DIM.	65 mm	67 mm	67 mm	66 mm	66 mm	67 mm	

Х

FORTH ROAD BRIDGE

DIMENSION OF SPRING PRE-COMPRESSION							
NORTH WEST(MAINSPAN)	MWI	MW2	MW3	MW4	MW5	MW6	
ROCKER PLT. SPRING COMPRESSION DIM.	140 mm	139 mm	141 mm	139 mm	139 mm	138 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	70 mm	70 mm	71 mm	72 mm	69 mm	71 mm	
TONGUE PLT. SPRING /W COMPRESSION DIM.	70 mm	71 mm	71 mm	69 mm	71 mm	70 mm	
DIMENSION OF SPRING CHECK							
NORTH WEST(SIDESPAN)	SWI	SW2	SW3	SW4	SW5	SW6	
ROCKER PLT. SPRING COMPRESSION DIM.	140 mm	140 mm	140 mm	138 mm	139 mm	140 mm	
TONGUE PLT. SPRING /E COMPRESSION DIM.	74 mm	75 mm	75 mm	76 mm	76 mm	76 mm	
TONGUE PLT. SPRING /W COMPRESSION DIM.	72 mm	76 mm	76 mm	77 mm	77 mm	75 mm	