

# **General Inspection Report**

(BC16)  
REPORT No.130  
SUSPENDERS

DATE: 17/12/2002 TO 18/12/2002

THE ROPES, SPACERS AND TOP CHORD ASSEMBLIES ON THE SIDE SPANS AND MAIN SPAN, BOTH EAST & WEST WERE VISUALLY INSPECTED OVER THE ABOVE DATES, AND WHERE REQUIRED THE USE OF OPTICAL AID EQUIPMENT FOR DETAILED INSPECTION CARRIED OUT.

GENERALLY THESE ITEMS WERE FOUND TO BE IN A SATISFACTORY CONDITION WITH NO DEFECTS REPORTED ON THE STRUCTURE REPORT PROGRAMME.

**INSPECTORS. :**