

# General Inspection Report

(BC06)

REPORT No.24

EXPANSION JOINT

DATE: 19/01/1998 TO 04/02/1998

THE SOUTH (DEMAG) MAIN & SIDE SPAN EXPANSION JOINTS WERE VISUALLY INSPECTED OVER AN INTERMITTANT PERIOD OF 3 TO 4 WEEKS , GENERAL FINDINGS AS FOLLOWS :

## STRUCTURALLY

ALL STRENGTHENING MEMBERS ,STIFFENING & ASSOCIATED STEELWORK FOUND TO BE SATISFACTORY ALLTHOUGH THERE WAS A DEGREE OF CORROSION EVIDENT .

## FIXINGS

MINOR DEFECTS LISTED UNDER STRUCTURE No 8212

## DEMAG SURFACE PLATE

ONLY 18 PANELS OUT OF 48 FOUND TO HAVE DEFECTS EVIDENT , RECORDED ON SURVEY SHEET & ISSUED.

INSPECTORS :