

General Inspection Report

(BC06)

REPORT No.26

EXPANSION JOINT

DATE: 11/11/1997 TO 18/11/1997

THE NORTH (VIADUCT) EXPANSION JOINTS WERE VISUALLY INSPECTED OVER AN INTERMITTANT PERIOD OF 7 DAYS, GENERAL FINDINGS AS FOLLOWS :

STRUCTURALLY

STEELWORK FOUND TO BE SATISFACTORY ALLTHOUGH MINOR CORROSION AND PAINT BREAKDOWN FOUND ON UNDERSIDES.

FIXINGS

LOOSE & MISSING NUTS RECORDED ON DEFECTS STRUCTURE No 8209, ALSO SIGNS OF MEDIUM CORROSION ON ALL UNDERSIDE FIXINGS .

DRAINAGE

EVIDENCE OF SLIGHT CORROSION ON TROUGH .

INSPECTORS :