

CABLE BAND REPLACEMENT BOLTS
NORTH EAST SIDESPAN

<u>P.P. 22 N.E.</u> BOLT SCAN 184/ BAND 1 CRACKED NUT BOLT No. 94 NEW BOLT No. 22 NEW L-REF= 662.01mm GAIN VALUE= 170 TEMP. AT TIME OF READING= 20° C BOLT No. RAC 0065 NUT(short end) RACN 0224 NUT RACN 0104	<u>P.P. 32 N.E.</u> BOLT SCAN 184/ BAND 2 CRACKED NUT BOLT No. 133 NEW BOLT No. 2 NEW L-REF= 661.69mm GAIN VALUE= 165 TEMP. AT TIME OF READING= 20° C BOLT No. RAC 0258 NUT(short end) RACN 0552 NUT RACN 0591
<u>P.P. 26 N.E.</u> BOLT SCAN 184/ BAND 3 CRACKED NUT BOLT No. 25 NEW BOLT No. 146 NEW L-REF= 662.50mm GAIN VALUE= 157 TEMP. AT TIME OF READING= 20° C BOLT No. RAC 0037 NUT(short end) RACN 0400 NUT RACN 0236	<u>P.P. 42 N.E.</u> BOLT SCAN 184/ BAND 3 CRACKED NUT BOLT No. 70 NEW BOLT No. 147 NEW L-REF= 661.33mm GAIN VALUE= 158 TEMP. AT TIME OF READING= 22° C BOLT No. RAC 0063 NUT(short end) RACN 0054 NUT RACN 0101
<u>P.P. 18 N.E.</u> BOLT SCAN 184/ BAND 3 CRACKED NUT BOLT No. 111 NEW BOLT No. 2 NEW L-REF= 662.24mm GAIN VALUE= 165 TEMP. AT TIME OF READING= 21° C BOLT No. RAC 0148 NUT(short end) RACN 0147 NUT RACN 0043	<u>P.P. 34 N.E.</u> BOLT SCAN 184/ BAND 2 CRACKED NUT BOLT No. 92(DEFECT) BOLT SCAN 184/ BAND 1 NEW BOLT No. 17 NEW L-REF= 660.98mm GAIN VALUE= 143 TEMP. AT TIME OF READING=20° C BOLT No. RAC 0202 NUT (short end) RACN 0197 NUT RACN 0276