



1. EXISTING WELD NOT GROUND OUT.
2. EXISTING WELD NOT GROUND OUT.
3. LACK OF FUSION BETWEEN RUNS.
4. UNTIDY START POINT.
5. LENGTH OF CRACK INDICATED BY YELLOW MARKER,
NO +50mm EITHER SIDE.

