



INSPECTION DEPARTMENT DEMAG MONTHLY INSPECTION DATE: 31/03/09

NORTH WEST SIDE SPAN	ROCKER PLATE SPRINGS & PINS	PINS & BUSHES	TONGUE PLATE SPRINGS & PINS
S.W. 1	OK	IN LOCATION	SECURE
S.W. 1	OK	IN LOCATION	SECURE
S.W. 2 S.W. 3	OK	IN LOCATION	E & W SPRINGS BROKEN BUT SECURE
S.W. 3	OK	IN LOCATION	SECURE
S.W. 4 S.W. 5	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
S.W. 5 S.W. 6	OK	IN LOCATION	E & W SPRINGS SPLIT BUT SECURE
NORTH EAST SIDE SPAN	- OK	INLOCATION	E & W SPRINGS SPLIT BUT SECURE
S.E. 6	OK	IN LOCATION	SECURE
S.E. 5	OK	IN LOCATION	E & W SPRINGS BROKEN BUT SECURE
S.E. 3	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
S.E. 3	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
S.E. 2	OK	IN LOCATION	SECURE
S.E. 2	OK	IN LOCATION	E SPRING SPLIT BUT SECURE
NORTH WEST MAIN SPAN	OK	IN LOCATION	E SERING SELLI BUT SECORE
M.W. 1	OK	IN LOCATION	SECURE
M.W. 2	OK	IN LOCATION	SECURE
M.W. 2	OK	IN LOCATION	SECURE
M.W. 3	OK	IN LOCATION	SECURE
M.W. 4	OK	IN LOCATION	SECURE
M.W. 5	OK	IN LOCATION	SECURE
	OK	INLOCATION	JECORE
M.E. 6	OK	IN LOCATION	E & W SPRINGS BROKEN BUT SECURE
M.E. 5	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
M.E. 3	OK	IN LOCATION	W SPRING BROKEN BUT SECURE
M.E. 3	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
M.E. 3 M.E. 2	OK	IN LOCATION	SECURE
M.E. 2 M.E. 1	OK	IN LOCATION	E & W SPRINGS SPLIT BUT SECURE
SOUTH WEST SIDE SPAN	ÖK	IN LOCATION	
S.W. 6	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
S.W. 5	OK	IN LOCATION	SECURE
S.W. 3	OK	IN LOCATION	W SPRING SPLIT BUT SECURE
S.W. 3	OK	IN LOCATION	E & W SPRINGS SPLIT BUT SECURE
S.W. 2	OK	IN LOCATION	E & W SPRINGS BROKEN. EAST LOOSE
S.W. 1	OK	IN LOCATION	W SPRING BROKEN BUT SECURE
SOUTH EAST SIDE SPAN		IN LOCATION	
S.E. 1	OK	IN LOCATION	SECURE
S.E. 2	OK	IN LOCATION	W SPRING BROKEN BUT SECURE
S.E. 3	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
S.E. 4	OK	IN LOCATION	W SPRING BROKEN BUT SECURE
S.E. 5	OK	IN LOCATION	W SPRING BROKEN BUT SECURE
S.E. 6	OK	IN LOCATION	SECURE
SOUTH WEST MAIN SPAN			
M.W. 6	MOVEMENT IN PIN	IN LOCATION	SECURE
M.W. 5	OK	IN LOCATION	W SPRING BROKEN BUT SECURE
M.W. 4	OK	IN LOCATION	W SPLIT/ E BROKEN MOVEMENT A
M.W. 3	OK	IN LOCATION	SECURE
M.W. 3	OK	IN LOCATION	E SPLIT BROKEN BUT SECURE
M.W. 2 M.W. 1	OK	IN LOCATION	W SPLIT BROKEN BUT SECURE
SOUTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E SPLIT BROKEN BUT SECURE
M.E. 2	OK	IN LOCATION	SECURE
M.E. 3	OK	IN LOCATION	W SPRING BROKEN BUT SECURE
M.E. 3	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
M.E. 5	OK	IN LOCATION	E & W SPRINGS SPLIT BUT SECURE
M.E. 6	OK	IN LOCATION	E SPRING BROKEN BUT SECURE
Signed			
- griod		I	

Created by lc/G:\Inspection Records\FETA Main Expansion Joint Inspection Reports -FOI\Main Tower Demag Expansion Joints - AW ongoing\Independent Inspections\Monthly Inspections. 2009. 2010\1 Demag Monthly Inspection 31.03.09.doc





INSPECTION DEPARTMENT
DEMAG MONTHLY
INSPECTION
DATE: 31/03/09

Created by lc/G:\Inspection Records\FETA Main Expansion Joint Inspection Reports -FOI\Main Tower Demag Expansion Joints - AW ongoing\Independent Inspections\Monthly Inspections. 2009. 2010\1 Demag Monthly Inspeciton 31.03.09.doc