



INSPECTION DEPARTMENT

MONTHLY DEMAG

DATE: 19/05/10

****CHANGES FROM PREVIOUS INSPECTIONS IN RED****

	ROCKER PLATE		
NORTH WEST SIDE SPAN	SPRINGS & PINS	PINS & BUSHES	TONGUE PLATE SPRINGS & PINS
S.W. I	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 3	OK	IN LOCATION	ÓK
S.W. 4	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.W. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN			
S.E. I	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	OK
S.E. 3	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE) W SPLIT
S.E. 5	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. 6	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. I	OK	IN LOCATION	E+W SPRING SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	OK
M.W. 4	ОК	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 6	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN			
M.E. I			
M.E. 2			
M.E. 3	NO ACCE	SS DHE TO E	LOORING BEING REMOVED
M.E. 4	NO ACCE	.33 DOL 10 I	LOOKING BLING KLMOYLD
M.E. 5			
M.E. 6			
SOUTH WEST SIDE SPAN			
S.W. I	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. 3	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 4	OK	IN LOCATION	OK
S.W. 5	OK	IN LOCATION	OK
S.W. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN			
S.E. I	OK	IN LOCATION	E+W SPRINGS SPLIT & LOOSE (PIN SECURE)
S.E. 2	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 3	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING SPLIT; PIN & SPRING ROTATES
S.E. 5	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST MAIN SPAN			
M.W. I	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	W SPRING SPLIT (SECURE) E SPLIT
M.W. 4	OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK	IN LOCATION	W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN	G.Y.	11.1.0.0.1.21.01.1	F. VA (CDD IN LOC CD) IT (CFC) ID T
M.E. I	OK	IN LOCATION	E+WSPRINGS SPLIT (SECURE)
M.E. 2	OK	IN LOCATION	OK
M.E. 3	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 4	OK	IN LOCATION	E SPRING BROKEN LOOSE (PIN SECURE ONLY BY PAINT & DIRT)
M.E. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. 6	OK	IN LOCATION	E SPRING BROKEN W SPRING SPLIT (SEC)
Signed by Inspectors:			





INSPECTION DEPARTMENT

MONTHLY DEMAG

DATE: 19/05/10

Forth Estuary

Transport Authority

NOTE: BROKEN DENOTES PART MISSING. SPLIT DENOTES FRACTURE TO SPRING. SECURE DENOTES NO MOVEMENT