



INSPECTION DEPARTMENT DEMAG MONTHLY INSPECTION

DATE: 03/05/09

	ROCKER PLATE		TONGUE PLATE SPRINGS & PINS
NORTH WEST SIDE SPAN	SPRINGS & PINS	PINS & BUSHES	
S.W. 1	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 3	OK	IN LOCATION	OK
S.W. 4	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	OK	IN LOCATION	OK
S.W. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN			
S.E. 1	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	
S.E. 3	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. 4	OK	IN LOCATION	
S.E. 5	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. 6	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	
M.W. 4	OK		E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 6	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN	OK		E. SPLIT/W. BROKEN(WITH MOVEMENT, PIN SECURE)
M.E. 1 M.E. 2	OK OK	IN LOCATION IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK OK	IN LOCATION	OK
_	OK OK		W SPRING BROKEN (SECURE)
M.E. 4	OK OK		
M.E. 5 M.E. 6	OK OK	IN LOCATION IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
SOUTH WEST SIDE SPAN	UK	INLOCATION	E+W SPRINGS SPLIT (SECURE)
S.W. 1	ОК	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. 1	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. 2	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 3	OK	IN LOCATION	OK
S.W. 5	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN	ÖR	IN LOCATION	
S.E. 1	ОК	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	OK
S.E. 3	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. 5	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. 6	OK	IN LOCATION	OK
SOUTH WEST MAIN SPAN			
M.W. 1	ОК	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	ОК	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	OK
M.W. 4	OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK	IN LOCATION	E SPRING SPLIT/W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.E. 2	ОК	IN LOCATION	OK
M.E. 3	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 4	ОК	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE
Signed by Inspector:			

lcG:\Inspection Records\FETA Main Expansion Joint Inspection Reports - FOI\Main Tower Demag Expansion Joints - AW ongoing\Independent Inspections\Monthly Inspections. 2009. 2010\2 Demag Monthly Inspection 03.05.09.doc





INSPECTION DEPARTMENT

DEMAG MONTHLY INSPECTION

DATE: 03/05/09

Transport Authority FORTH ROAD BRIDGE NOTE: BROKEN DENOTES PART MISSING. SPLIT DENOTES FRACTURE TO SPRING. SECURE DENOTES NO MOVEMENT.

lcG:\Inspection Records\FETA Main Expansion Joint Inspection Reports - FOI\Main Tower Demag Expansion Joints - AW ongoing\Independent Inspections\Monthly Inspections. 2009. 2010\2 Demag Monthly Inspection 03.05.09.doc