



INSPECTION DEPARTMENT

DEMAG MONTHLY
INSPECTION

DATE: 03/05/09

NORTH WEST SIDE SPAN	ROCKER PLATE	DING & DUGUES	TONGUE PLATE SPRINGS & PINS
NORTH WEST SIDE SPAN	SPRINGS & PINS	PINS & BUSHES	E OPPINIO PROMEN (OFOURE)
S.W. 1	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 2	OK OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 3	OK	IN LOCATION	OK
S.W. 4	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	OK	IN LOCATION	OK
S.W. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN			
S.E. 1	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	OK
S.E. 3	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.E. 5	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. 6	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	OK
M.W. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 6	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E. SPLIT/W. BROKEN(with movement, pin secure)
M.E. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK	IN LOCATION	OK
M.E. 4	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
M.E. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
SOUTH WEST SIDE SPAN			
S.W. 1	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. 3	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 4	OK	IN LOCATION	OK
S.W. 5	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN	OV	INLLOCATION	W ODDING ODLIT (OFOLIDE)
S.E. 1	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	OK ORDING PROVEN (SECURE)
S.E. 3	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 4	OK OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. 5	OK OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. 6 SOUTH WEST MAIN SPAN	OK	IN LOCATION	OK
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK OK	IN LOCATION	OK
M.W. 4	OK OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK OK	IN LOCATION IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT (SECURE) E SPRING SPLIT/W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN	IVIOVEIVIEINT IIN FIIN	IIN LOCATION	L OI NING OFLIT (SECURE)
M.E. 1	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.E. 2	OK OK	IN LOCATION	OK
M.E. 3	OK OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 4	OK OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. 6	OK OK	IN LOCATION	E SPRING SPLIT (SECURE
Signed by Inspector:) Oit	III LOOATION	1 2 31 Kill O SI EII (OLOOKE
	ART MISSING SPLIT DEN	OTES FRACTURE TO SE	RING. SECURE DENOTES NO MOVEMENT
HOTE. BROKEN DENOTES I	AITT MICOING, OF EIT DEN	OTEOTRACIONE TO SP	MINO. OLOGIC DENOTES NO WOVEWENT.





INSPECTION DEPARTMENT

DEMAG MONTHLY INSPECTION

DATE: 03/05/09