



## **INSPECTION DEPARTMENT**

**DEMAG MONTHLY INSPECTION** 

DATE: 01/06/09

	ROCKER PLATE		TONGUE PLATE SPRINGS & PINS
NORTH WEST SIDE SPAN	SPRINGS & PINS	PINS & BUSHES	
S.W. <b>1</b>	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. <b>3</b>	OK	IN LOCATION	OK
S.W. <b>4</b>	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. <b>5</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.W. <b>6</b>	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN			· · · · · · · · · · · · · · · · · · ·
S.E. <b>1</b>	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. <b>2</b>	OK	IN LOCATION	OK
S.E. <b>3</b>	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.E. <b>5</b>	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. <b>6</b>	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. 1	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	OK
M.W. <b>4</b>	OK OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. <b>5</b>	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. <b>6</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN	J.Y.		
M.E. 1	OK	IN LOCATION	E. SPLIT/W. BROKEN(with movement, pin secure)
M.E. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. <b>4</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. <b>5</b>	OK	IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
M.E. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST SIDE SPAN	OIC .	IIV EGG/(TIGIV	E OF TRIVE OF EIT (OLOGICE)
S.W. 1	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. <b>3</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. <b>4</b>	OK	IN LOCATION	OK
S.W. <b>5</b>	OK OK	IN LOCATION	OK OK
S.W. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN	OIC .	IIV EGG/(TIGIV	E GI KING GI EII (GEGGKE)
S.E. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. <b>2</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. <b>3</b>	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.E. <b>4</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. <b>5</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST MAIN SPAN		IN LOOKTION	E STRING OF EIT (OLOGICE)
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. <b>2</b>	OK OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 4	OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK OK	IN LOCATION	W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN	IVIO V LIVILINI IIN F IIN	IN LOCATION	L OF KING OF LIT (OLOOKL)
M.E. 1	OK	IN LOCATION	E+WSPRINGS SPLIT (SECURE)
M.E. 2	OK OK	IN LOCATION	OK
M.E. 3	OK OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 4	OK OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. <b>5</b>	OK OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. <b>6</b>	OK OK	IN LOCATION	E SPRING BROKEN W SPRING SPLIT (SEC)
	UN.	IN LOCATION	L OF KING DROKEN W SPRING SPLIT (SEC)
Signed by Inspector:	ART MISSING SPLIT DEN	OTES EDACTURE TO SE	PRING. SECURE DENOTES NO MOVEMENT
NOTE. PROMENDENOTES P	ART MISSING, SPEIT DEN	OTES PRACTURE TO SI	KING. SECORE DENOTES NO MOVEMENT.

Created by lc/G:\Inspection Records\FETA Main Expansion Joint Inspection Reports - FOI\Main Tower Demag Expansion Joints - AW ongoing\Independent Inspections\Monthly Inspections. 2009. 2010\3 Demag Monthly Inspection 01.06.09.doc





**INSPECTION DEPARTMENT** 

**DEMAG MONTHLY INSPECTION** 

DATE: 01/06/09