



INSPECTION DEPARTMENT

DEMAG MONTHLY INSPECTION

DATE: 01/06/09

	ROCKER PLATE		TONGUE PLATE SPRINGS & PINS
NORTH WEST SIDE SPAN	SPRINGS & PINS	PINS & BUSHES	
S.W. 1	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 3	OK	IN LOCATION	OK
S.W. 4	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.W. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN			
S.E. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	OK
S.E. 3	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.E. 5	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. 6	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. 1	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	OK
M.W. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 6	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E. SPLIT/W. BROKEN(WITH MOVEMENT, PIN SECURE)
M.E. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. 4	OK	IN LOCATION	W SPRING BROKEN (SECURÉ)
M.E. 5	OK	IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
M.E. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST SIDE SPAN	J .,		
S.W. 1	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. 3	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 4	OK	IN LOCATION	OK
S.W. 5	OK OK	IN LOCATION	OK
S.W. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN	OIX	INTEGRATION	E OF KING OF EFF (OLGONE)
S.E. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 3	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.E. 4	OK OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. 5	OK OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. 6	OK OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST MAIN SPAN	OK .	IN LOCATION	L OF KING OF LIT (OLCOKE)
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 4	OK OK	IN LOCATION IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK MOVEMENT IN DIN	IN LOCATION	W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN M.E. 1	OK	IN LOCATION	ET/MSDDINGS SDLIT (SECURE)
			E+WSPRINGS SPLIT (SECURE)
M.E. 2	OK OK	IN LOCATION	OK
M.E. 3	OK OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 4	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. 6	OK	IN LOCATION	E SPRING BROKEN W SPRING SPLIT (SEC)
Signed by Inspector:			
NOTE: BROKEN DENOTES P	ART MISSING. SPLIT DEN	OTES FRACTURE TO SE	PRING. SECURE DENOTES NO MOVEMENT





INSPECTION DEPARTMENT

DEMAG MONTHLY INSPECTION

DATE: 01/06/09