



INSPECTION DEPARTMENT

DEMAG MONTHLY INSPECTION

DATE: 03/07/09

NORTH WEST SIDE SPAN	ROCKER PLATE	PINS & BUSHES	TONGUE PLATE SPRINGS & PINS
S.W. 1	SPRINGS & PINS OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 1	OK OK	IN LOCATION	E SPRING BROKEN (SECURE)
	OK OK		,
S.W. 3 S.W. 4		IN LOCATION	OK ORDINGS PROVEN (SECURE)
_	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	OK	IN LOCATION	OK
S.W. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN	OV	INLLOCATION	E CODING COLIT (CECLIDE)
S.E. 1 S.E. 2	OK	IN LOCATION IN LOCATION	E SPRING SPLIT (SECURE)
S.E. 3	OK		OK ORDING PROVEN A DI ACEC (CECURE)
	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. 4	OK OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.E. 5	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. 6	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN	OK	INLLOCATION	F.W. CDDINGS CDLIT (CCCUDE)
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2 M.W. 3	OK OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 4	OK	IN LOCATION	OK E SPRING PROVEN/POTATING (DIN OFCURE)
	OK OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5 M.W. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN M.E. 1	OK	IN LOCATION	E. SPLIT/W. BROKEN(WITH MOVEMENT, PIN SECURE)
M.E. 2	OK OK	IN LOCATION IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK OK	IN LOCATION IN LOCATION	OK
M.E. 4	OK OK	IN LOCATION IN LOCATION	W SPRING BROKEN (SECURE)
	OK OK	IN LOCATION IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
M.E. 5 M.E. 6	OK OK	IN LOCATION IN LOCATION	E+W SPRINGS SPLIT (SECURE)
SOUTH WEST SIDE SPAN	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.W. 1	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. 2	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 4	OK	IN LOCATION	OK
S.W. 5	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN	OR	IN ECCATION	E SI KING SI EII (SESSIKE)
S.E. 1	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. 2	OK OK	IN LOCATION	OK
S.E. 3	OK OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. 5	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.E. 6	OK	IN LOCATION	OK
SOUTH WEST MAIN SPAN	J	200, 0	
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	OK
M.W. 4	OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK	IN LOCATION	E SPRING SPLIT/W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.E. 2	OK	IN LOCATION	OK
M.E. 3	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 4	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE
Signed by Inspector:			
NOTE: BROKEN DENOTES P	ART MISSING. SPLIT DEN	OTES FRACTURE TO SI	PRING. SECURE DENOTES NO MOVEMENT





INSPECTION DEPARTMENT

DEMAG MONTHLY INSPECTION

DATE: 03/07/09

IT SHOULD BE RECORDED THAT ON THE NORTH WEST MAIN SPAN A TOTAL OF 4 in No SPRINGS WERE REPLACED DURING THE INSPECTION OF THE EXPANSION PLATES ON THE EVENING OF 16/01/09.

- MW 2 TONGUE PLATE EAST SPRING REPLACED
- MW 3 TONGUE PLATE EAST & WEST SPRING REPLACED
- MW 4 TONGUE PLATE WEST SPRING REPLACED