



INSPECTION DEPARTMENT
MONTHLY DEMAG
DATE: 01/09/09

	ROCKER PLATE		TONCHE DI ATE SERINCS & DINIS
NORTH WEST SIDE SPAN	SPRINGS & PINS	PINS & BUSHES	TONGUE PLATE SPRINGS & PINS
S.W. 1	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. <b>2</b>	OK OK	IN LOCATION	OK
S.W. <b>3</b>	OK OK		9
		IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. <b>5</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.W. <b>6</b>	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN	014	11.1.00ATION	LE IM ODDINGO ODLIT (OFOLIDE)
S.E. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	OK
S.E. <b>3</b>	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE) W SPLIT
S.E. <b>5</b>	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. <b>6</b>	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. <b>1</b>	OK	IN LOCATION	E+W SPRING SPLIT (SECURE)
M.W. <b>2</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. <b>3</b>	OK	IN LOCATION	OK
M.W. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. <b>5</b>	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. <b>6</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E. SPLIT/W. BROKEN(with movement ,pin secure)
M.E. <b>2</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. <b>4</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. <b>5</b>	OK	IN LOCATION	E.BROKENW. SPLIT (ALL SECURE)
M.E. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST SIDE SPAN	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. 1	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. <b>3</b> S.W. <b>4</b>			
	OK	IN LOCATION	OK OK
S.W. <b>5</b>	OK	IN LOCATION	OK
S.W. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN	014	INITION	E W OPPINION OPLIT (OFFILIPE)
S.E. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 3	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. <b>5</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST MAIN SPAN			
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. <b>2</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. <b>3</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE) E SPLIT
M.W. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. <b>5</b>	OK	IN LOCATION	W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E+WSPRINGS SPLIT (SECURE)
M.E. <b>2</b>	OK	IN LOCATION	OK
M.E. <b>3</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. <b>5</b>	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. 6	OK	IN LOCATION	E SPRING BROKEN W SPRING SPLIT (SEC)
Signed by Inspector:		200/11014	1 2 3. 14.14 B.14.14 W OF 14.14 OF LIT (010)
	T MISSING SPLIT DENOT	ES FRACTURE TO S	PRING. SECURE DENOTES NO MOVEMENT
PROMEN DENOTES PAR	T MICOING. OF EIT DENOT	LOT MACTORE TO 3	TRING, GEOGRE DENOTED NO MOVEMENT





INSPECTION DEPARTMENT

MONTHLY DEMAG DATE: 01/09/09