



INSPECTION DEPARTMENT	

MONTHLY DEMAG DATE: 06/10/09

## PLEASE NOTE THERE ARE NO CHANGES FROM PREVIOUS INSPECTION.

NORTH WEST SIDE SPAN	ROCKER PLATE SPRINGS & PINS	PINS & BUSHES	TONGUE PLATE SPRINGS & PINS
S.W. I	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. <b>3</b>	OK	IN LOCATION	ÓK
S.W. <b>4</b>	ОК	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.W. <b>6</b>	ОК	IN LOCATION	E+W SPRINGS SPLIT (SECÚRE)
NORTH EAST SIDE SPAN			
S.E. I	ОК	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. <b>2</b>	OK	IN LOCATION	OK
S.E. <b>3</b>	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE) W SPLIT
S.E. <b>5</b>	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. <b>6</b>	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. I	OK	IN LOCATION	E+W SPRING SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. <b>3</b>	OK OK	IN LOCATION	OK
M.W. <b>4</b>	OK OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
	OK OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5			
M.W. 6	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN	01/		
M.E. I	OK	IN LOCATION	E. SPLIT/W. BROKEN (WITH MOVEMENT, PIN SECURE)
M.E. <b>2</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. <b>4</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. <b>5</b>	OK	IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
M.E. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST SIDE SPAN			
S.W. I	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. <b>3</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. <b>4</b>	OK	IN LOCATION	OK
S.W. <b>5</b>	OK	IN LOCATION	OK
S.W. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN			
S.E. I	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. <b>2</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. <b>3</b>	OK	IN LOCATION	E+W SPRINGS BROKEN (SECÚRE)
S.E. <b>4</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. <b>5</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST MAIN SPAN			
M.W. I	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. <b>2</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	W SPRING SPLIT (SECURE) E SPLIT
M.W. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK	IN LOCATION	W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN			
M.E. I	OK	IN LOCATION	E+WSPRINGS SPLIT (SECURE)
M.E. <b>2</b>	OK	IN LOCATION	OK
M.E. <b>3</b>	OK OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. <b>4</b>	OK OK	IN LOCATION IN LOCATION	E SPRING BROKEN (SECURE) E+W SPRINGS SPLIT (SECURE)
M.E. <b>5</b> M.E. <b>6</b>	OK OK	IN LOCATION	E SPRING BROKEN W SPRING SPLIT (SEC)

G:\dd\t&p\rnmmd\branch8\FRBFOI~1\25A97~1.INS\FETAMA~1\MAINTO~1\SPECIA~1\MONTHL~1\6 Demag Monthly Inspection 06.10.09.doc





INSPECTION DEPARTMENT	-
MONTHLY DEMAG	
DATE: 06/10/09	