



INSPECTION DEPARTMENT
MONTHLY DEMAG

DATE: 17/11/09

PLEASE NOTE THERE ARE NO CHANGES FROM PREVIOUS INSPECTION.

| | ROCKER PLATE | | TONGUE PLATE SPRINGS & PINS |
|-------------------------|-----------------------|------------------|--|
| NORTH WEST SIDE SPAN | SPRINGS & PINS | PINS & BUSHES | |
| S.W. I | OK | IN LOCATION | E SPRING BROKEN (SECURE) |
| S.W. 2 | OK | IN LOCATION | E SPRING BROKEN (SECURE) |
| S.W. 3 | OK | IN LOCATION | OK |
| S.W. 4 | OK | IN LOCATION | E+W SPRINGS BROKEN (SECURE) |
| S.W. 5 | OK OK | IN LOCATION | W SPRING SPLIT (SECURE) |
| S.W. 6 | OK OK | IN LOCATION | E+W SPRINGS SPLIT (SECURE) |
| NORTH EAST SIDE SPAN | OK. | INLOCATION | ETTY STRINGS SEET (SECORE) |
| S.E. I | OK | IN LOCATION | E+W SPRINGS SPLIT (SECURE) |
| S.E. 2 | OK OK | IN LOCATION | OK |
| S.E. 3 | OK OK | IN LOCATION | E SPRING BROKEN 2 PLACES (SECURE) |
| S.E. 4 | OK OK | IN LOCATION | E SPRING BROKEN/ROTATING (PIN SECURE) W SPLIT |
| S.E. 5 | OK OK | IN LOCATION | E +W SPRINGS BROKEN (ALL SECURE) |
| S.E. 6 | OK OK | IN LOCATION | OK |
| NORTH WEST MAIN SPAN | OK . | INLOCATION | OK . |
| M.W. I | OK | IN LOCATION | E+W SPRING SPLIT (SECURE) |
| M.W. 2 | OK OK | IN LOCATION | W SPRING SPLIT (SECURE) |
| | | | , |
| M.W. 3 | OK OK | IN LOCATION | OK CRIDING PROVEN (POTATING (PA) (SECURE) |
| M.W. 4 | OK | IN LOCATION | E SPRING BROKEN/ROTATING(PIN SECURE) |
| M.W. 5 | OK | IN LOCATION | E+W SPRINGS SPLIT (SECURE) |
| M.W. 6 | OK | IN LOCATION | W SPRING SPLIT (SECURE) |
| NORTH EAST MAIN SPAN | 21/ | 11.1.0.04.7.01.1 | F COLUTAN PROVEN |
| M.E. I | OK | IN LOCATION | E. SPLIT/W. BROKEN (WITH MOVEMENT, PIN SECURE) |
| M.E. 2 | OK | IN LOCATION | W SPRING SPLIT (SECURE) |
| M.E. 3 | OK | IN LOCATION | E SPRING BROKEN (SECURE) |
| M.E. 4 | OK | IN LOCATION | W SPRING BROKEN (SECURE) |
| M.E. 5 | OK | IN LOCATION | E.BROKEN/W. SPLIT (ALL SECURE) |
| M.E. 6 | OK | IN LOCATION | E + W SPRING SPLIT (SECURE) |
| SOUTH WEST SIDE SPAN | | | |
| S.W. I | OK | IN LOCATION | E SPRING SPLIT, W BROKEN (ALL SECURE) |
| S.W. 2 | OK | IN LOCATION | E SPRING BROKEN/ROTATING (PIN SECURE) |
| S.W. 3 | OK | IN LOCATION | E SPRING SPLIT (SECURE) |
| S.W. 4 | OK | IN LOCATION | OK |
| S.W. 5 | OK | IN LOCATION | OK |
| S.W. 6 | OK | IN LOCATION | E SPRING SPLIT (SECURE) |
| SOUTH EAST SIDE SPAN | | | |
| S.E. I | OK | IN LOCATION | E+W SPRINGS SPLIT (SECURE) |
| S.E. 2 | OK | IN LOCATION | W SPRING BROKEN (SECURE) |
| S.E. 3 | OK | IN LOCATION | E+W SPRINGS BROKEN (SECURE) |
| S.E. 4 | OK | IN LOCATION | E SPRING SPLIT (SECURE) |
| S.E. 5 | OK | IN LOCATION | W SPRING BROKEN (SECURE) |
| S.E. 6 | OK | IN LOCATION | E SPRING SPLIT (SECURE) |
| SOUTH WEST MAIN SPAN | | 11.11.0.01.=:0.1 | E NA CORDINA CO CRISTA (OF CURTA) |
| M.W. I | OK | IN LOCATION | E+W SPRINGS SPLIT (SECURE) |
| M.W. 2 | OK | IN LOCATION | E SPRING SPLIT (SECURE) |
| M.W. 3 | OK | IN LOCATION | W SPRING SPLIT (SECURE) E SPLIT |
| M.W. 4 | OK | IN LOCATION | E SPRING BROKEN (LOOSE) W SPLIT(SECURE) |
| M.W. 5 | OK | IN LOCATION | W SPRING BROKEN(SEC) |
| M.W. 6 | MOVEMENT IN PIN | IN LOCATION | E SPRING SPLIT (SECURE) |
| SOUTH EAST MAIN SPAN | | | |
| M.E. I | OK | IN LOCATION | E+WSPRINGS SPLIT (SECURE) |
| M.E. 2 | OK | IN LOCATION | OK |
| M.E. 3 | OK | IN LOCATION | W SPRING BROKEN (SECURE) |
| M.E. 4 | OK | IN LOCATION | E SPRING BROKEN (SECURE) |
| M.E. 5 | OK | IN LOCATION | E+W SPRINGS SPLIT (SECURE) |
| M.E. 6 | OK | IN LOCATION | E SPRING BROKEN W SPRING SPLIT (SEC) |
| Signed by Inspectors: | | | |
| NOTE: BROKEN DENOTES PA | RT MISSING. SPLIT DEN | OTES FRACTURE T | O SPRING. SECURE DENOTES NO MOVEMENT |
| | | | |