



INSPECTION DEPARTMENT

MONTHLY DEMAG

DATE: 23/02/10

## PLEASE NOTE THERE ARE NO CHANGES FROM PREVIOUS INSPECTION.

	ROCKER PLATE		TONGUE PLATE SPRINGS & PINS
NORTH WEST SIDE SPAN	SPRINGS & PINS	<b>PINS &amp; BUSHES</b>	
S.W. I	ОК	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. <b>3</b>	OK	IN LOCATION	ОК
S.W. 4	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	ОК	IN LOCATION	W SPRING SPLIT (SECURE)
S.W. <b>6</b>	ОК	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN			
S.E. I	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. <b>2</b>	OK	IN LOCATION	ОК
S.E. <b>3</b>	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE) W SPLIT
S.E. <b>5</b>	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. <b>6</b>	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. I	OK	IN LOCATION	E+W SPRING SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 3	ОК	IN LOCATION	ОК
M.W. <b>4</b>	ОК	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5	ОК	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 6	ОК	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN			
M.E. I	OK	IN LOCATION	E. SPLIT/W. BROKEN(WITH MOVEMENT , PIN SECURE)
M.E. <b>2</b>	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.E. <b>3</b>	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. <b>4</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
M.E. <b>6</b>	OK	IN LOCATION	E + W SPRING SPLIT (SECURE)
SOUTH WEST SIDE SPAN			
S.W. I	OK	IN LOCATION	E SPRING SPLIT, W BROKEN (ALL SECURE)
S.W. <b>2</b>	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE)
S.W. <b>3</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.W. <b>4</b>	OK	IN LOCATION	OK
S.W. <b>5</b>	OK	IN LOCATION	OK
S.W. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST SIDE SPAN			
S.E. I	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. <b>2</b>	ОК	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. <b>3</b>	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.E. <b>4</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
S.E. <b>5</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. <b>6</b>	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST MAIN SPAN			
M.W. I	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	W SPRING SPLIT (SECURE) E SPLIT
M.W. <b>4</b>	ОК	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	ОК	IN LOCATION	W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN			
M.E. I	OK	IN LOCATION	E+WSPRINGS SPLIT (SECURE)
M.E. <b>2</b>	OK	IN LOCATION	ОК
M.E. <b>3</b>	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. <b>4</b>	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. <b>5</b>	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. <b>6</b>	OK	IN LOCATION	E SPRING BROKEN W SPRING SPLIT (SEC)
Signed by Inspectors:			
NOTE: BROKEN DENOTES PA	RT MISSING. SPLIT DEN	IOTES FRACTURE T	O SPRING. SECURE DENOTES NO MOVEMENT