

CHANGES FROM PREVIOUS INSPECTIONS IN RED

NORTH WEST SIDE SPAN	ROCKER PLATE SPRINGS & PINS	PINS & BUSHES	TONGUE PLATE SPRINGS & PINS
S.W. 1	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 2	OK	IN LOCATION	E SPRING BROKEN (SECURE)
S.W. 3	OK	IN LOCATION	OK
S.W. 4	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.W. 5	OK	IN LOCATION	W SPRING SPLIT (SECURE)
S.W. 6	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
NORTH EAST SIDE SPAN			
S.E. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	OK
S.E. 3	OK	IN LOCATION	E SPRING BROKEN 2 PLACES (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING (PIN SECURE) W SPLIT
S.E. 5	OK	IN LOCATION	E +W SPRINGS BROKEN (ALL SECURE)
S.E. 6	OK	IN LOCATION	OK
NORTH WEST MAIN SPAN			
M.W. 1	OK	IN LOCATION	E+W SPRING SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	OK
M.W. 4	OK	IN LOCATION	E SPRING BROKEN/ROTATING(PIN SECURE)
M.W. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 6	OK	IN LOCATION	W SPRING SPLIT (SECURE)
NORTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E. SPLIT/W. BROKEN(WITH MOVEMENT ,PIN SECURE)
M.E. 2	OK	IN LOCATION	W SPRING SPLIT (SECURE)
M.E. 3	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. 4	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E.BROKEN/W. SPLIT (ALL SECURE)
M.E. 6	OK	IN LOCATION	E + W SPRING SPLIT (SECURE)
SOUTH WEST SIDE SPAN			
S.W. 1	NO ACCESS; 50% OF FLOOR GRATINGS REMOVED BY SGB		
S.W. 2			
S.W. 3			
S.W. 4			
S.W. 5			
S.W. 6			
SOUTH EAST SIDE SPAN			
S.E. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
S.E. 2	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 3	OK	IN LOCATION	E+W SPRINGS BROKEN (SECURE)
S.E. 4	OK	IN LOCATION	E SPRING SPLIT; PIN & SPRING ROTATES
S.E. 5	OK	IN LOCATION	W SPRING BROKEN (SECURE)
S.E. 6	OK	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH WEST MAIN SPAN			
M.W. 1	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.W. 2	OK	IN LOCATION	E SPRING SPLIT (SECURE)
M.W. 3	OK	IN LOCATION	W SPRING SPLIT (SECURE) E SPLIT
M.W. 4	OK	IN LOCATION	E SPRING BROKEN (LOOSE) W SPLIT(SECURE)
M.W. 5	OK	IN LOCATION	W SPRING BROKEN(SEC)
M.W. 6	MOVEMENT IN PIN	IN LOCATION	E SPRING SPLIT (SECURE)
SOUTH EAST MAIN SPAN			
M.E. 1	OK	IN LOCATION	E+WSPRINGS SPLIT (SECURE)
M.E. 2	OK	IN LOCATION	OK
M.E. 3	OK	IN LOCATION	W SPRING BROKEN (SECURE)
M.E. 4	OK	IN LOCATION	E SPRING BROKEN (SECURE)
M.E. 5	OK	IN LOCATION	E+W SPRINGS SPLIT (SECURE)
M.E. 6	OK	IN LOCATION	E SPRING BROKEN W SPRING SPLIT (SEC)
Signed by Inspectors:			
NOTE: BROKEN DENOTES PART MISSING. SPLIT DENOTES FRACTURE TO SPRING. SECURE DENOTES NO MOVEMENT			