



#### **INSPECTION DEPARTMENT**

"A" Line WEST Main Span Engineer Defects

DATE: 08/12/09



### P.P.51 S.W.

**CENTRE TRI-DUCT LOOSE** 



#### P.P.67 S.W.

PIPE HANGER/LINDAPTOR LOOSE – ADJACENT TO WIND DEFLECTOR (IST HANGER SOUTH OF P.P.)



#### P.P.73 S.W.

**EAST TRI-DUCT LOOSE** 



### P.P.76 S.W.

LOOSE HANGER/LINDAPTOR I<sup>ST</sup> HANGER NORTH OF P.P. ADJACENT TO WIND DEFLECTOR





#### **INSPECTION DEPARTMENT**

"A" Line WEST Main Span Engineer Defects DATE: 08/12/09



## P.P.79 S.W.

**EAST TRI-DUCT LOOSE** 



### P.P.78 N.W.

**EAST TRI-DUCT LOOSE** 



# P.P.70 N.W.

EAST TRI-DUCT LOOSE