



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.01.14

North West Main Span:

- PP 48 - All stringers ok with packers in place, satisfactory - quiet
- PP 50 - All stringers ok with packers in place, satisfactory - quiet
- PP 52 - All stringers ok with packers in place, satisfactory - quiet
- PP 54 - Stringer nos. 1, 2 & 3 packers worn. Stringer no. 4 ok – **Noisy**
- PP 56 - Stringer no. 1 packer worn. Stringer nos. 2, 3 & 4 ok
- PP 58 - All stringers ok with packers in place, satisfactory - quiet
- PP 60 - Ok – this was replaced as part of the half joint trial that was undertaken by Raynesway.
- PP 62 - Stringers 1, 2 & 3 showing signs of wear. Stringer no. 4 ok - **monitor**
- PP 64 - Stringer nos. 1 & 2 packers worn. Stringer nos. 3 & 4 ok – **Noisy**
- PP 66 - All stringers ok with packers in place, satisfactory - quiet
- PP 68 - All stringers ok with packers in place, satisfactory - quiet
- PP 70 - Stringer nos. 1 & 3 packers worn. Stringer nos. 2 & 4 ok – **Noisy**
- PP 72 - All stringers ok with packers in place, satisfactory - quiet
- PP 74 - All stringers ok with packers in place, satisfactory - quiet
- PP 76 - All stringers ok with packers in place but showing slight signs of wear – **monitor**
- PP 78 - Stringer nos. 1 & 2 packers worn. Stringers 3 & 4 ok – **Noisy**
- PP 80 - All stringers ok with packers in place, satisfactory - quiet
- PP 82 - All stringers ok with packers in place but showing slight signs of wear – **monitor**
- PP 84 - All stringers ok with packers in place, satisfactory - quiet
- PP 86 - All stringers ok with packers in place, satisfactory - quiet
- PP 88 - Stringer nos. 1, 3 & 4 packers worn. Stringer no. 2 ok – **Noisy**
- PP 90 - All stringers ok with packers in place, satisfactory - quiet



INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.01.14

North West Main Span cont.....:

- PP 92 - Stringer nos. 1 & 2 packers worn. Stringer nos. 3 & 4 ok – **Noisy**
- PP 94 - All stringers ok with packers in place, satisfactory - quiet
- PP 96 - Stringer nos. 1 through to 4 packers worn – **Noisy**
- PP 98 - All stringers ok with packers in place, satisfactory - quiet
- PP 100 - All stringers ok with packers in place but showing slight signs of wear – **monitor**

South West Main Span:

- PP 48 - All stringers ok with packers in place, satisfactory - quiet
- PP 50 - All stringers ok with packers in place, satisfactory - quiet
Stringer no. 3 has a sheared bolt on the east face
- PP 52 - Stringer nos. 1 through to 4 packers worn – **Noisy**
- PP 54 - Stinger nos. 1 through to 4 packers worn – **Noisy**
- PP 56 - All stringers ok with packers in place, satisfactory - quiet
- PP 58 - All stringers ok with packers in place, satisfactory - quiet
- PP 60 - All stringers ok with packers in place, satisfactory - quiet
- PP 62 - All stringers ok with packers in place, satisfactory - quiet
- PP 64 - All stringers ok with packers in place, satisfactory - quiet
- PP 66 - All stringers ok with packers in place, satisfactory - quiet



FORTH ROAD BRIDGE

PP 68 - All stringers ok with packers in place, satisfactory - quiet

INSPECTION DEPARTMENT
Billet Survey Main Span (West)
DATE. 2013.01.14

South Main Span cont....:

PP 70 - All stringers ok with packers in place, satisfactory - quiet

PP 72 - All stringers ok with packers in place, satisfactory - quiet

PP 74 - Stringer nos. 1 & 2 packers worn. Stringer nos. 3 & 4 ok – **Noisy**

PP 76 - All stringers ok with packers in place, satisfactory - quiet

PP 78 - All stringers ok with packers in place, satisfactory - quiet

PP 80 - Stringer nos. 1 through to 4 packers worn – **Noisy**

PP 82 - Stringer nos. 2 & 3 packers worn. Stringer nos. 1 & 4 ok – **Noisy**

PP 84 - Stringer no. 2 packer worn. Stringer nos. 1, 3 & 4 ok – **monitor**

PP 86 - All stringers ok with packers in place, satisfactory - quiet

PP 88 - All stringers ok with packers in place, satisfactory - quiet

PP 90 - All stringers ok with packers in place, satisfactory - quiet

PP 92 - Stringer nos. 1 & 2 packers worn. Stringer nos. 3 & 4 ok – **Noisy**

PP 94 - All stringers ok with packers in place, satisfactory - quiet

PP 96 - All stringers ok with packers in place, satisfactory - quiet

PP 98 - All stringers ok with packers in place, satisfactory - quiet

PP 100 - All stringers ok with packers in place, satisfactory - quiet