




INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.01.19



Comments. :

On the Northbound Carriageway (West Side) NW2 - noise evident when heavy vehicles pass over

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise still evident on east side of SW1, further repairs required

Inspectors. :

Date.:



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.01.19