



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.01.27

N

North. West.

North. East.

✓	X	✓	✓	✓	✓	✓	✓	C E N T R A  L  R E S E R V A T I O N	✓		✓	✓	✓	X	✓	✓	✓
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1	

South. West.

South. East.

X	✓	✓	✓	✓	✓	✓	✓	C E N T R A  L  R E S E R V A T I O N	✓	✓	✓	✓	X	✓	✓	✓
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1

N

Comments. :

On the Northbound Carriageway (West Side) NW2 – movement/noise evident when heavy vehicles pass over  
 On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise still evident on east side of SW1, further repairs required

On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over

Inspectors. : ..... Date.: .....



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.01.27