




INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.01.27



Comments. :

On the Northbound Carriageway (West Side) NW2 – movement/noise evident when heavy vehicles pass over
 On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise still evident on east side of SW1, further repairs required
 On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over

Inspectors. : Date.:



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.01.27