

Comments. :

On the Northbound Carriageway (West Side) NW2 – movement/noise evident when heavy vehicles pass over On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over - spring pack to be replaced

Inspectors. : Date.:

H:\Viaduct Expansion Joint Weekly Inspections 2015\Combe Plate Weekly Survey Sheet 2015.02.03.Doc

INSPECTION DEPARTMENT

FORTH ROAD BRIDGE

Combe plate weekly survey sheet DATE. 2015.02.03