

On the Northbound Carriageway (West Side) NW2 – movement/noise evident when heavy vehicles pass over On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over - spring pack to be replaced

Inspectors. : Date.:

G:\Inspection Records\FETA Inspection Reports On Joints - FOI\Viaduct Expansion (Combe) Joints\Independent Inspections\Combe Plate Weekly Survey Sheet 2015.02.03.Doc



Combe plate weekly survey sheet DATE. 2015.02.03



G:\Inspection Records\FETA Inspection Reports On Joints - FOI\Viaduct Expansion (Combe) Joints\Independent Inspections\Combe Plate Weekly Survey Sheet 2015.02.03.Doc