




INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.03.16



Comments. :

On the Northbound Carriageway (West Side) NW2 – movement/noise evident when heavy vehicles pass over  
 On the Southbound Carriageway NE4 – movement/noise evident when heavy vehicles pass over

On the Northbound Carriageway (West Side) SW1 – repair previously carried out 06.01.15 by Engineers – noise was still evident on east side of SW1 - spring packs replaced on SW1 and SW2, further works to be carried out  
 On the Southbound Carriageway SE4 – movement/noise evident when heavy vehicles pass over  
 Southbound Carriageway SE2 – there is slight movement on the west side.

Inspectors. : ..... Date.: .....



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.03.16