



INSPECTION DEPARTMENT

Combe plate weekly survey
sheet

DATE. 2015.11.17..

North. West.								North. East.								
✓	✓	✓	✓	✓	✓	✓	✓	CENTRAL RESERVATION	✓		✓	✓	✓	✓	✓	✓
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1
South. West.								South. East.								
✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	X	✓	
1	2	3	4	5	6	7	8	8	7	6	5	4	3	2	1	

Comments. : **Combe plate NE4. Repaired during program of works Week- end 31/10/15. By engineer K. Horn.**

On the Southbound Carriageway

Southbound Carriageway SE2 – there is slight movement / slight noise evident – will monitor. **Plate noisier on this inspection will require attention soon.**

Northbound Carriageway – All plates satisfactory.

Inspectors. :

Date.:



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.11.17..