



INSPECTION DEPARTMENT

Combe plate weekly survey
sheet

DATE. 2015.11.24.

North. West.									North. East.								
✓	✓	✓	✓	✓	✓	✓	✓	CENTRAL RESERVATION	✓		✓	✓	✓	✓	✓	✓	
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1	
South. West.										South. East.							
✓	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	X	X	
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1	

Comments. :

On the Southbound Carriageway

Southbound Carriageway SE2 – there is slight movement / slight noise evident – will monitor. Plate noisier on this inspection will require attention soon.

Southbound Carriageway SE1 – Very noisy this inspection requires to be repaired A.S.A.P.

Northbound Carriageway – All plates satisfactory.



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.11.24.