



INSPECTION DEPARTMENT

Combe plate weekly survey
sheet

DATE. 2015.11.30.

North. West.								North. East.								
✓	✓	✓	✓	✓	✓	✓	✓	CENTRAL RESERVATION	✓		✓	✓	✓	✓	✓	✓
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1
South. West.									South. East.							
✓	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	X	X
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1

N

N

Comments. :

On the Southbound Carriageway

Southbound Carriageway SE2 – there is slight movement / slight noise evident – will monitor. Plate noisier on this inspection will require attention soon.

Southbound Carriageway SE1 – Very noisy this inspection requires to be repaired A.S.A.P. (Repair works carried out Wednesday N/ shift 25/11/2015.) Movement & Noise still evident on plate No 1. Further works require to plate No 1.

Northbound Carriageway – All plates satisfactory.



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.11.30.