



INSPECTION DEPARTMENT

Combe plate weekly survey
sheet

DATE. 2015.12.29..

North. West.								North. East.									
✓	✓	✓	✓	✓	✓	✓	✓	CENTRAL RESERVATION	✓		✓	✓	X	✓	✓	✓	✓
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1	
South. West.									South. East.								
✓	✓	✓	✓	✓	✓	✓	✓		✓	✓	✓	✓	✓	✓	✓	✓	✓
1	2	3	4	5	6	7	8		8	7	6	5	4	3	2	1	

Comments. : Bridge closed this inspection. Visual only carried out.

On the Southbound Carriageway.- Combe plate N.E 5 movement and noise evident on the west side of the combe plate, requires repair

Northbound Carriageway – All plates satisfactory.

Inspectors. :

Date.:



INSPECTION DEPARTMENT
Combe plate weekly survey sheet
DATE. 2015.12.29..