



North west side span

1. PP. 20 , Bolt “ D” live side. **Bolt “D” replaced 27/04/12.**
2. PP. 20 , Bolt “ B” Live side. -- (Found on requested monthly inspection 4/4/12) **Bolt “B” replaced 25/04/12.**
3. PP. 24 , Bolt “ D” dead side.
4. PP. 26 , Bolt “A” Live side.
5. PP. 38 , Bolt “ F” Live side.

North east side span

1. PP. 22 , Bolt “ F” dead side.
2. PP. 28 , Bolt “ F” Live side.
3. PP. 36 , Bolt “ H” Live side.

Main span North west.

1. PP. 78. Bolt “ D” dead side.

Main span North east.

- 1. PP. 54. Bolt “ D” Live side.**
- 2. PP. 54. Bolt “ B” dead side. (Both bolts replaced Sunday 25/03/12)**

Main span South east.

1. PP. 78. Bolt “ B” Live side.

Main span South west.

1. PP. 52. Bolt “ A” dead side.
2. PP. 80. Bolt “ B” dead side.

South west side span

1. PP. 24 , Bolt “ D” Live side. **Bolt “D” replaced 15/05/12.**
2. PP. 24 , Bolt “ B” Live & Dead side.

14 bolt locations with 15 defective nuts

INSPECTION DEPARTMENT
Defective nut locations.
DATE.



INSPECTION DEPARTMENT
Defective nut locations.
DATE.