

The main tower cycle track expansion joints were inspected on the above date, general findings as follows:

Current status remains as previous inspections with deterioration continuation on the sliding plates & apron plates and cycle track wearing surface below.

Steelwork / Fittings / fixings. : All structural steelwork & fixings remain in a satisfactory condition. Minor corrosion / discolouration apparent on bolt-heads located under the cycle track.

Tensioning Assemblies: No further investigation carried out this inspection with regard to current status of cycle track expansion joints assembly packs.

All defects recorded & entered on structure report programme.

Inspectors. :

Note.: Information . : During a meeting with the maintenance manager, subject of the cycle track expansion joints was raised . It was during this meeting that information was given that the aforementioned expansion joints would included for replacement as part of the capital works plan to replace the Main- tower carriageway expansion joints. (De-mags)