

INSPECTION DEPARTMENT

MONTHLY EXPANSION JOINT FAILSAFE SYSTEM.

DATE: 19.07.12

Expansion Joint Failsafe System

| | ROCKER PLATE | | |
|----------------------|----------------|--------------------|---|
| NORTH WEST SIDE SPAN | SPRINGS & PINS | FIXINGS | TONGUE PLATE SPRINGS & PINS |
| S.W. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| NORTH EAST SIDE SPAN | | | |
| S.E. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| NORTH WEST MAIN SPAN | | | |
| M.W. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 4 | SATISFACTORY | SATISFACTORY | BROKEN SPRING – WEST SIDE - SECURE |
| M.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| NORTH EAST MAIN SPAN | | | |
| M.E. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH WEST SIDE SPAN | | | |
| S.W. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH EAST SIDE SPAN | | | |
| S.E. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 3 | SATISFACTORY | SATISFACTORY | SMALL SECTION OF TOP BROKEN AWAY - SECURE |
| S.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH WEST MAIN SPAN | | | |
| M.W. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH EAST MAIN SPAN | | | |
| M.E. I | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 6 | JATISI ACTORT | 37 (11317 (C1 C1(1 | |