



INSPECTION DEPARTMENT

MONTHLY EXPANSION
JOINT FAILSAFE SYSTEM.

DATE: 2013.06.07

Expansion Joint Failsafe System

| NORTH WEST SIDE SPAN | ROCKER PLATE SPRINGS & PINS | FIXINGS | TONGUE PLATE SPRINGS & PINS |
|-----------------------------|--------------------------------|--------------|---|
| S.W. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| NORTH EAST SIDE SPAN | | | |
| S.E. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| NORTH WEST MAIN SPAN | | | |
| M.W. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| NORTH EAST MAIN SPAN | | | |
| M.E. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH WEST SIDE SPAN | | | |
| S.W. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH EAST SIDE SPAN | | | |
| S.E. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 3 | SATISFACTORY | SATISFACTORY | CRACKED SPRING – WEST SIDE – REMAINS SECURE |
| S.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| S.E. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH WEST MAIN SPAN | | | |
| M.W. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.W. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| SOUTH EAST MAIN SPAN | | | |
| M.E. 1 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 2 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 3 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 4 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 5 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| M.E. 6 | SATISFACTORY | SATISFACTORY | IN LOCATION AND SATISFACTORY. |
| Signed by Inspector : | | | |