



Expansion Joint Failsafe System

INSPECTION DEPARTMENT
MONTHLY EXPANSION JOINT FAILSAFE SYSTEM.
DATE: 2015.06.22.

NORTH WEST SIDE SPAN	ROCKER PLATE SPRINGS & PINS	FIXINGS	TONGUE PLATE SPRINGS & PINS
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
NORTH EAST SIDE SPAN			
S.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	CRACKED SPRING – REMAINS IN TENSION & SECURE
S.E. 6	SATISFACTORY	SATISFACTORY	CRACKED SPRING – REMAINS IN TENSION & SECURE
NORTH WEST MAIN SPAN			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
NORTH EAST MAIN SPAN			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH WEST SIDE SPAN			
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH EAST SIDE SPAN			
S.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH WEST MAIN SPAN			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	CRACKED SPRING – REMAINS IN TENSION & SECURE
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH EAST MAIN SPAN			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
Signed by Inspector :			
2. in No New defective springs found this inspection. N/E Side-span cell 6 (west spring) S/W. Main-span Cell 5 (east spring)			