



## Expansion Joint Failsafe System

INSPECTION DEPARTMENT

MONTHLY EXPANSION  
JOINT FAILSAFE SYSTEM.

DATE: 2015.07.28.

NORTH WEST SIDE SPAN	ROCKER PLATE SPRINGS & PINS	FIXINGS	TONGUE PLATE SPRINGS & PINS
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
NORTH EAST SIDE SPAN			
S.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 2	SATISFACTORY	SATISFACTORY	<b>CRACKED SPRING – REMAINS IN TENSION &amp; SECURE</b>
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	<b>CRACKED SPRING – REMAINS IN TENSION &amp; SECURE</b>
S.E. 6	SATISFACTORY	SATISFACTORY	<b>CRACKED SPRING – REMAINS IN TENSION &amp; SECURE</b>
NORTH WEST MAIN SPAN			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
NORTH EAST MAIN SPAN			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH WEST SIDE SPAN			
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH EAST SIDE SPAN			
S.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH WEST MAIN SPAN			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	<b>CRACKED SPRING – REMAINS IN TENSION &amp; SECURE</b>
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH EAST MAIN SPAN			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.

Signed by Inspector :

2. in No. defective springs to be replaced from last inspection date. : N/E Side-span cell 6 ( west spring ) S/W. Main-span Cell 5 ( east spring ) 22/06/2015.

1 in No new spring found this inspection. N/E Side-span Cell SE2 ( east spring.) 28/07/15.